



Service Bulletin

Bulletin No.: 24-NA-005

Date: January, 2024

TECHNICAL

Subject: Headlamps Flashing and/or DTC P0606 Set in Lighting Control Module

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500HD/ 3500HD	2024	2024				
GMC	Sierra 2500HD/ 3500HD	2024	2024				

Involved Region or Country	North America, Middle East, Israel, Australia, New Zealand.
Additional Options (RPOs)	
Condition	Some customers may comment on the headlamps flashing and/or the windshield wiper pausing while wiping. Technicians may find DTC P0606 in the Lighting Control Module set current or in recent history.
Cause	The causes of the condition may be that a low battery state of charge can cause voltage diagnostics to fail in the Lighting Control Module. If the battery goes below the threshold in the Lighting Control Module during a cranking event or battery discharged that needs a jump start, the Lighting Control Module may go into a reset every 8-10 seconds, causing the headlamps to flash.
Correction	DO NOT replace the Lighting Control Module for this condition. Test the battery using the instruction in Service Information Battery Inspection/Test. Replace the battery if it fails. Note: Disconnecting the battery will reset the Lighting Control Module and erase the P0606 and correct the flashing headlamps.

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*2086928	Test Battery and Reset the Lighting Control Module	0.4 hr
Add	If the Vehicle is Equipped with an Auxiliary Battery	0.2 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	Released January 10, 2024

